



## Report of the United States Geological Survey to the Secretary of the Interior Volume 3

By Geological Survey

Rarebooksclub.com, United States, 2012. Paperback. Book Condition: New. 246 x 189 mm. Language: English . Brand New Book \*\*\*\*\* Print on Demand \*\*\*\*\*.This historic book may have numerous typos and missing text. Purchasers can download a free scanned copy of the original book (without typos) from the publisher. Not indexed. Not illustrated. 1893 Excerpt: .The end of this is protected by wooden planking for abutments, and from it the weir extends to the left bank of the river, opposite the canal head. In the center of this weir are seven openings, each 6 feet wide. The work is founded on piles sunk 10 feet into the gravel bed of the stream, the crest of the weir being 5 feet 6 inches above the grade of the canal. The total length of the weir is 80 feet from bank to bank. The Monte Vista weir (Fig. 90) gives a better idea of the form of construction of these weirs. It consists of an earth embankment, about 16 feet long, resting on the left bank of the river. Jutting into the stream at an angle with this is a crib dam, built essentially as is the open sluiceway, but filled in with...



**READ ONLINE**  
[ 2.1 MB ]

### Reviews

*A top quality publication along with the font used was intriguing to read. I really could comprehend everything using this written e book. Its been designed in an remarkably straightforward way and it is only after i finished reading through this publication by which basically altered me, modify the way i believe.*

-- **Cathrine Larkin Sr.**

*Very useful to all of group of people. I actually have read through and so i am certain that i will planning to study yet again once again down the road. I am just very easily can get a satisfaction of looking at a created book.*

-- **Mark Bernier**